ABSTRACT

A microelectromechanical system (MEMS) strain gauge includes at least one flexible arm that can be caused to oscillate. Transverse strain on the arm changes the resonant frequency of the arm, providing an indication of the transverse strain of the substrate.

MKE/5470702.doc